

Project UT1202 Kaw Water Treatment Plant Traveling Water Screen Rehabilitation



Traveling water screen head unit with new torque tube and chain sprockets installed.



Boot section with new lower chain sprockets and bushings installed



Corroded and worn intermediate frame rail and chain guide



Corroded intermediate frame rail